Dart Aerospace Ltd. Monday, 2/5/2007 8:06:55 AM Kim Johnston **Process Sheet** : A119 STEP WELDMENT LH Drawing Name : CU-DAR001 Dart Helicopters Services Customer Job Number : 30591 : 10122 **Estimate Number** : D3043041 Part Number P.O. Number : NA S.O. No. : NIA D3043 REV A **Drawing Number** : 2/5/2007 This Issue Project Number : N/A : NC Prsht Rev. : MA : LARGE FAB ASSY **Drawing Revision** First Issue : NA : 28654 Material Previous Run Each Due Date : 2/7/2007 Qty: 1 Um: Written By Checked & Approved By JLM 05-11-01 : Est Rev New Issue Comment **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: Extrusion D26221200 1.0 Comment: Otv.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick:D2622-120 extrusion Batch: 🔏 LARGE FABRICATION RESOURCE 1 2.0 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2622-120 extrusion to 120.00" long as per Dwg D3043 using cutting table setup DT8185-G 2-Deburr and bevel ends for welding INSPECT WORK TO CURRENT STEP 3.0 QC5 07.02 Comment: INSPECT WORK TO CURRENT STEP 206 Step Endplate 4.0 D2734 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Qty Part Number Description Batch End Cap D30401 Mounting Lug 5.0 Comment: Qtv.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3040-1 Mounting Lug 384405

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGE	ES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·	
 							
Part No	•	PAR #: Fault Category:	NCR: Yes	No DO	Δ.	Date:	

Part No:	_ PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Annroyal	Annessal		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
•										
							i			
		•								
				·						
···										
						,				
				%* *						

Monday, 2/5/2007 8:06:55 AM Date: Kim Johnston User: **Process Sheet** Drawing Name: A119 STEP WELDMENT LH Customer: CU-DAR001 Dart Helicopters Services Job Number: 30591 Part Number: D3043041 Job Number: Description: Seq. #: Machine Or Operation: Mounting Lug 6.0 D30403 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Qty Part Number Description Batch Mounting Lug B34406 2 D3040-3 7.0 LARGE FAB Comment: LARGE FABRICATION RESOURCE 1 1-Weld 1 End Cap & Mounting Lugs as per QSI 004 & Dwg D3043 Using DT8802 AL ROD Batch: <u>M/60337</u> M/03395 2-Grind Fwd End Cap weld flush VISUAL WELDING INSPECTION 8.0 QC9 Comment: VISUAL WELDING INSPECTION INSPECT WORK TO CURRENT STEP 9.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 HAND FINISHING 10:0 Comment: HAND FINISHING RESOURCE #1 07/02/05 1-Chemical Conversion Coat as per QSI 005 4.1 LARGE FABRICATION RESOURCE 1 11.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-1-Weld 1 End Cap as per QSI 004 & Dwg D3043 AR AL ROD Batch: MIGO 237 2-Inspect for foreign object as per QSI 024

3-Grind Fwd End Cap weld flush

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	P PROCEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				,							
				•			:				
Part No	:	PAR #: Fault Category: NO	CR: Ye	s No DQ	A:	Date: _					
			QA:	: N/C Close	d:	Date: _					

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	A ======1	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng			
							:			
							·			
								·		
					:					
								_		

	nday, 2/5/2007 8:06:55 AM	•	'k		•
User : Kin	n Johnston	Proces	s Sheet		
Customer	: CU-DAR001 Dart Helico	pters Services	Drawing Name: A119 STEP \	WELDMENT LH	
,			•		
Job Number	· 30591		Part Number: D3043041		
Job Number:			T di Citalipoli.	<u>:</u>	
JOD Number.					
Seq. #:	Machine Or Operation:		Description :		
12.0	QC9	VISUAL WE	LDING INSPECTION		
		 			
. 4			<u>, </u>		\rightarrow
Comm	ent: VISUAL WELDING	INSPECTION		1107/02/06	(a)
13.0	QC5	INSPECT W	ORK TO CURRENT STEP	/ /	
Comm	ent: INSPECT WORK TO			11/07/02	106 (I)
14.0	HAND FINISHING1	HAND FINIS	SHING RESOURCE #1	/ 	\mathcal{L}
					(1)
Comm	ent: HAND FINISHING F	RESOURCE #1	m 1 h		2-1-10
		10 : : : 0 : : : : : : : : : : : : : : :	//////////////////////////////////		07/02/00
15.0	,	al Conversion Coat as per QSI 005	OWDER COAT/CHEMICAL CONVE	ERCION	
15.0		INSPECT P	OWDER COAT/CHEMICAL COINVE		
Comm	ent: INCRECT DOWNER	IIIII COAT/CHEMICAL CONVERSIO	NI	Λ	
	Inspect alodine	, COATIONE MICAL CONVENCIO	14	Moza	2/00
16.0	POWDER COATING	POWDER C	OATING	1000	2/00//
Comm	ent: POWDER COATING			/ /	
		Gloss (Ref: 4.3.5.1) as per QSI 00	5 4.3	12/02/06	(0)
17.0	HAND FINISHING1		SHING RESOURCE #1		
		 			
					·
Commo	ent: HAND FINISHING R	ÉSOURCE #1	1 2 11		۰
				12/	2/04/1
<u></u> .		Dwg D3043 and QSI 005 4.4		01/6	12/08
18.0	QC3	INSPECT PO	OWDER CONTICHEMICAL CONVE	ERSION /	
			_		
		COAT/CHEMICAL CONVERSIO		100/08	//
19.0	PACKAGING 1	PACKAGING	RESOURCE#1		
			•		
		UDOF #4	.*14		
Comme	ent: PACKAGING RESO	URUE #1	/ /	~	
	Identify and Stock Location:	//1/01/	12/10/1		
	LUCATION.		100/ CO(/)		·
			/		
		/			

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGE	ES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·					
	c						
Part No	:	PAR #: Fault Category:	NCR: Yes	MO DQ	N.S.	Date: _	07/00/06
			QA:	N/C Closed	1:	_ Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Annroyal	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng			
										

Date:

Monday, 2/5/2007 8:06:55 AM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: A119 STEP WELDMENT LH

Job Number: 30591

Part Number: D3043041

Job Number:



Seq. #:

Machine Or Operation:

Description:

20.0

QC21

FINAL INSPECTION/W/O RELEASE



Job Completion



W 07-02 De

Dart Ae	rospace	Ltd								
W/O:			WC	RK ORDER CHAN	IGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									P *** 1	
					•					
Part No	:	PAR #:	Fault Categ	jory:	NCI	R: Yes	No DQ	A :	_ Date: _	
						QA: N	I/C Close	d:	Date:	
NCR:		,	WORK ORDE	R NON-CONFORM	MANCE	(NCR	R)			
		Description of NC		Corrective Action S	ection B		Verific	ation	Approval	pproval Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
				·						
								1		





DESIG	ip	DRAWN BY	DART AEROSPACE US	SA, INC.
CHECK	(ED M)	APPROVED	DRAWING NO.	REV. A
	#	1	D3043	SHEET 1 OF 2
DATE			TITLE	SCALE
01'.0	6.28		A119 STEP WELDMENT	NTS
Α		01.06.28	NEW ISSUE	


PARTS LIST:

Qty -041_	Qty -043	Part Number	Description	
Х		D3043-041	STEP WELDMENT, LH	
	Х	D3043-042	STEP WELDMENT, RH	
1	1	D2622-120	STEP EXTRUSION	
2	2	D3040-1	MOUNTING LUG	
2	2	D3040-3	MOUNTING LUG	
2	2	D2734	ENDPLATE	

NOTES:

- 1) MANUFACTURE FROM D2622-120 EXTRUSION
- 2) WELD PER DART QSI 004. ALL WELDS SHOULD BE 100% VISUALLY INSPECTED BY A QUALIFIED INSPECTOR PER DART QSI 004
- 3) FINISH: ACID ETCH & ALODINE ASSEMBLY PER DART QSI 005 4.1 POWDER COAT WHITE (REF 4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT TOP SURFACE OF STEP TO BOTTOM OF TOP RADIUS PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY RETURNTO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT



Copyright @ 2001 by DART AEROSPACE USA, INC.

-1-24405 3=24406 DESIGN DRAWN BY DART AEROSPACE USA. INC. PORT HADLOCK, WA CHECKED APPROVED DRAWING NO. REV. A D3043 SHEET 2 OF 2 TITLE SCALE DATÉ A119 STEP WELDMENT 01.06.28 1:5 Α 01.06.28 **NEW ISSUE** - 120.00 (DOES NOT INCLUDE ENDPLATES) --D3040-1 MOUNTING LUG 11.4 **ENSURE HOLES** (2 PLACES) (TYP) **ALIGN** -D3040-3 MOUNTING LUG (2 PLACES) 1.00 D2734 ENDPLATE 45 (TYP BOTH ENDS). 0.875 + 0.030 (TYP) 96.57 10.48 VIEW A-A: D3043-041 LH STEP WELDMENT - 120.00 (DOES NOT INCLUDE ENDPLATES) — D3040-1 MOUNTING LUG 11.4 **ENSURE HOLES** (2 PLACES) (TYP) **ALIGN** D3040-3 MOUNTING LUG (2 PLACES) 1.00 D2734 ENDPLATE (TYP BOTH ENDS) 0.875 +0.030 (TYP) 96.57 10.48 SHOP COPY RETURN TO ENGINEKRING UNCONTROLLED COPY SUBJECT TO MENDMENT

Copyright © 2001 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

RH

STEP WELDMENT

VIEW A-A: D3043-042